

RexXer EVO

Available service-functions of the different ECU-types

Release: August 2017 - © by RexXer

Tuning GmbH



RexXer EVO Service-Functions											
BRAND	ECU-Type	Read/Write/ D ECU	Read/Clear error codes: DTC	Firmware Info	TPS reset	Reset autoadaptive parameters	APS reset	CO trimming	Quickshifter reset	Waste throttle reset	Reset Service light
Adiva	Magneti Marelli MIU										
Aprilia	Magneti Marelli MIU										
	Magneti Marelli IAW 5AM							*			
	Magneti Marelli IAW 5DM							*			
	Magneti Marelli IAW 7SM							*			
BMW*	BOSCH BMSK ME9							*			
Derbi	Magneti Marelli MIU										
Ducati	Magneti Marelli 15M							*			
	Magneti Marelli IAW 59M										
	Magneti Marelli IAW 5AM										
	Magneti Marelli IAW 7SM							*			
	Conti VDO M3C							*			
	Mitsubishi MELCO							*			
Gas Gas	Magneti Marelli IAW 15P							*			
Gilera	Magneti Marelli IAW 15P							*			
	Magneti Marelli IAW 5AM										
	Magneti Marelli MIU										
KTM	Keihin							*			
KVN	Magneti Marelli IAW 15P							*			
Malaguti	Magneti Marelli MIU										
	Magneti Marelli IAW 15P							*			
Moto Guzzi	Magneti Marelli IAW 15RC							*			
	Magneti Marelli IAW 15M							*			
	Magneti Marelli IAW 5AM										
	Magneti Marelli MIU										
Moto Morini	Magneti Marelli IAW 5AM										
MV Agusta	Magneti Marelli IAW 5SM							*			
	Magneti Marelli IAW 7BM							*			
	Eldor							*			
Peugeot	Magneti Marelli MIU										
Piaggio	Magneti Marelli MIU										
Triumph	Keihin							*			
Vespa	Magneti Marelli MIU										
Voxan	Magneti Marelli IAW 15RC							*			

 Availabel
 Not available

* This function is not supported by the ECU!

RexXer Tuning GmbH / Astheimer Str. 41 | 65428 Rüsselsheim (Germany)
 Fon: +49 (0) 6142 / 793971-203 | Fax: +49 (0) 6142 / 793971-80 | Email: info@rexser.eu | Web: www.rexser.eu